



1 / 3



TITLE: METHOD FOR REPAIRING GAS TURBINE
COMPRESSOR ROTOR BLADES
INVENTOR: DOUGLAS P. BENETEAU, et al.
DOCKET: 134354
ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070

2/3




FIG. 3

TITLE: METHOD FOR REPAIRING GAS TURBINE
COMPRESSOR ROTOR BLADES
INVENTOR: DOUGLAS P. BENETEAU, et al.
DOCKET: 134354
ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070

3/3




FIG. 4